

# EPSON PRODUCT SUPPORT BULLETIN

<b>Date:</b>	10/08/2004	<b>Originator:</b>	DS
<b>PSB #:</b>	PSB.2004.10.003	<b>Authorization:</b>	Kps
<b>Reference:</b>	TE 04-0295, Rev. A	<b>Total Pages:</b>	2
<b>Product(s):</b>	The following products that use TDK's PHY chip. C82391*, C12C82402*, C12C82405*, EPSON Network Image Express Card		
<b>Subject:</b>	Compatibility of Cisco Catalyst 3560/3750/4500/6500 Series Switches/Hubs		

This bulletin was created to provide information concerning Cisco HUB/Switch products (including Network modules) and EPSON Print Servers that experience link problems when directly connected.

## **Cause:**

There is a limitation of the TDK chip to recognize the First-Link-Pulse (FLP) in Auto Negotiation. The Cisco products use PoE\*\* (Cisco Inline Power). When PoE and FLP are in use, Auto Negotiation cannot be established therefore a link cannot be established between the Switch/ HUB and the Print Server.

\*\* PoE (Power over Ethernet): This technology provides power over the Ethernet cable connection.

## **Countermeasure Plans:**

Auto Negotiation cannot be used in either the Switch/HUB or the Print Server because the Print Server uses link speed settings with Half or Full duplex on the Switch/HUB or Print Server.

- 1.) Disable the Cisco Inline Power on the Cisco Products HUB/Switch.  
The Cisco Inline Power is unnecessary for EPSON products Print Servers. The Epson products are provided power from either the printer slot or an AC Power Adapter.
- 2.) Connect another Switch/HUB between the Cisco product HUB/Switch and EPSON Print Server.

## **Target Products from Cisco:**

In the product matrix noted below where the "OK" is designated for the model of the Cisco Inline Power product, there is a possibility that the link problem will occur. However, when IEEE802.3af is used in the same product, it is possible that the problem will not occur.

\*\* The following list only corresponds to the Cisco Inline Power products.

\*\* Also, the following list is comprised of currently selling products.

The Cisco Inline Power products are included from 2000, therefore, there is a possibility the same problem will occur by the time of product discontinuation.

\*\* In the product where "Update" is noted to IEEE802.3af PoE in the following list, IEEE802.3af may be used with the updated module.

Catalyst6500 Series	Cisco Inline Power (Cisco original PoE●)	IEEE802.3af PoE (Standard)
WS-X6548-GE-45AF	OK	OK
WS-X6548V-GE-TX	OK	Upgrade
WS-X6548-GE-TX	OK	Upgrade
WS-X6148-GE-45AF	OK	OK
WS-X6148V-GE-TX	OK	Upgrade
WS-X6148-GE-TX	OK	Upgrade
WS-X6148X2-45AF	OK	OK
WS-X6148-45AF	OK	OK
WS-X6148-RJ45V	OK	
WS-X6148-21AF	OK	OK
WS-X6148-RJ21V	OK	
WS-X6148X2-RJ-45	OK	Upgrade
WS-X6348-RJ-45	OK	Upgrade
WS-X6348-RJ-21	OK	Upgrade
WS-X6348-RJ45V	OK	
WS-X6348-RJ21V	OK	
Catalyst4500 Series		
WS-X4548-GB-RJ45V	OK	OK
WS-X4148-RJ45V	OK	
WS-X4248-RJ21V	OK	OK
WS-X4248-RJ45V	OK	OK
Catalyst 3750-24PS-S	OK	OK
Catalyst 3750-24PS-E	OK	OK
Catalyst 3750-48PS-S	OK	OK
Catalyst 3750-48PS-E	OK	OK
Catalyst 3560-24PS-S	OK	OK
Catalyst 3560-24PS-E	OK	OK
Catalyst 3560-48PS-S	OK	OK
Catalyst 3560-48PS-E	OK	OK

\*\* Designation of Cisco In-Line Power and conformity to IEEE PoE

Cisco In-Line Power	PoE(Power over Ethernet)
- Cisco original standard. - Input 9W	- Conformity to IEEE802.3af standard - Input 15.4W