

EQUITY 386/33 PLUS					
VER	PART #	DESC	TYPE	LOC	REASON
031892	Y707590802	AMI	27C512	U29	INITIAL RELEASE
061892	201078300	AMI	27C512	U29	Rapid keystrokes on all areas of the keyboard may cause a shift key lock and/or keyboard lockup. In some rare cases, improper keyboard timing may cause intermittent system boot failure. See ECN No: EQ386/33+-001 (2/5/93).

ENDEAVOR / EQUITY 4					
VER	PART #	DESC	TYPE	LOC	REASON
1.149A		AWARD	27C010	U8	INITIAL RELEASE

ENDEAVOR 486C					
VER	PART #	DESC	TYPE	LOC	REASON
053193	1017670	AMI	27C010	U8	INITIAL RELEASE

EL 486 UC					
VER	PART #	DESC	TYPE	LOC	REASON
1.01	451-7010-201	PHOENIX	27C010	U20	INITIAL RELEASE