

Product Support Bulletin

Subject: C823021, C823032 I/F Data Loss

Date: 2/7/92

Page(s): 1 of 1

PSB No: P-0083

Originator: VB

The purpose of this document is to inform the consumer and retailer that the buffer size on the 32K Serial (C823021) and Parallel (C823032) Interface Boards, CANNOT be expanded. The current C823021 and C823032 User's Manuals indicate that the buffer CAN be increased and the current interface boards HAVE sockets for additional RAM chips. However, any attempt to expand the buffer may result in data loss. As of October 1991, all C823021 and C823032 interface boards will be manufactured WITHOUT the RAM expansion sockets. Also, the C823032 and C823021 User's Manuals will be amended to delete all references to expanding the buffer size. Existing inventories ARE NOT being modified to reflect this change.