

Home Cinema 3200

Home Cinema 3800

Release Notes

Version 1.07

Security update

To comply with the Radio Equipment Directive (RED), the following measures have been implemented:

1) Firmware Security

- Encryption of firmware
- Secure-supported firmware cannot be downgraded to non-secure firmware. If a downgrade is attempted, the device will remain in the download state (indicated by slow LED blinking) for over 10 minutes. After the ten minute time period of slow blinking, the download mode will end and the firmware will not update.

2) Whitelist Support for ESC/VP.net Commands to enhance security, to only allow applications and access sources that have been pre-approved. Block all other communications and access attempts. This whitelist approach also includes prohibiting the acceptance of specific commands.

The ESC/VP.net blocks (responds with an error) any command attempts to access security and network assets, related to: PLink, Web control, Monitor, Web Remote, Factory reset